

## TOGA instrument—Recommend spares and replacement criteria

15-Feb-11

The list which follows covers recommended spares and limited lifetime components in TOGA. A column of this table also contains inspection criteria to use in assessing when the component must be replaced.

| Brand/<br>Vendor | Model number                            | Description   | Inspection/failure criteria   | Approx<br>cost/each |
|------------------|---|---|---|---------------------|
| Omega            | STH051-040LSE                           | Heater for the CAG catalyst   | This must be replaced each time the CAG catalyst is opened, ~once/5 years                                   | \$50                |
| Omega            | PX176-100A5V                            | P transducer for pneumatic pump   | If complete failure, replace, zero or negative pressures will be read at failure                            | \$410               |
| Omega            | KMQSS-020U-12                           | Type K thermocouple probe, for traps and general use                                  | Reads open circuit upon failure   | \$60                |
| Omega            | TMQSS-062U-12                           | Type T, 1/16" thermocouple probe, for LN2 liquid measurement                          | Reads open circuit upon failure   | \$60                |
| Swagelok         | SS-4FW-2                                | 2 µm sintered stainless filter  | Contamination or excessive pressure drop  | \$40                |
| Swagelok         | SS-4BK-1C                               | pneumatic valve, normally closed  | Valve failure, intermittent behavior or failure to open or seal completely                                  | \$200               |
| Swagelok         | SS-4BK-1O                               | pneumatic valve, normally open  | Valve failure, intermittent behavior or failure to open or seal completely                                  | \$200               |
| Swagelok         | SS-4C-EP-10                             | Poppet valve  | Failure to open or seal completely  | \$50 ea             |
| Restek           | MXT 10mm, 0.18mm id                     | Metal gas chromatographic column  | Poor GC performance, peak tailing   | \$400               |
| Scott Specialty  | Calibration standard and GC column flow | 2-stage gas regulator, two in use   | Pressure fluctuations at the regulator gauge  | \$500               |
| General Air      | He purge and makeup air                 | 2-stage gas regulator, two in use   | Pressure fluctuations at the regulator gauge  | \$250               |
| NCAR             | --in house at NCAR--                    | Water trap, custom made, stainless steel, includes thermocouple probe and heater wire | Open circuit at thermocouple, short circuit between heater wire and TC or tubing, or open circuit of heater | 1-day of NCAR time  |
| NCAR             | --in house at                           | Sample trap, custom made, stainless   | Open circuit at thermocouple,   | 1-day of            |

|             |                      |   |  |                    |
|-------------|----------------------|---|--|--------------------|
|             | NCAR--               | steel, includes thermocouple probe, glass packing and heater wire                         | short circuit between heater wire and TC or tubing, or open circuit of heater  | NCAR time          |
| NCAR        | --in house at NCAR-- | Cryofocus trap, custom made, stainless steel, includes thermocouple probe and heater wire | Open circuit at thermocouple, short circuit between heater wire and TC or tubing, or open circuit of heater                      | 1-day of NCAR time |
| Valco       | various              | Valco hardware, unions, ferrules, etc   | New hardware needed at disassembly of traps, 10-port valves and SSV valves   | \$500              |
| Lenox laser | various              | Several critical orifices   | Blockage   | \$150              |
| Aldrich     | 23,211-4             | Platinum catalyst compound, Aldrich, 100 grams  | When clean air generator loses catalytic function (fails to generate adequate zero air) the catalyst must be replaced in the CAG | \$292              |

|                      |  |   |  |        |
|----------------------|--|---|--|--------|
| Intel                | DG43NB ATX   | 775 motherboard, exact form factor is critical for TOGA electronics box   | PC board failure/breakage  | \$295  |
| Intel                | Core 2 Duo<br>E8400<br>3 GHz<br>6MB<br>1333F<br>SB<br>CPU<br>and fan | PC processor and fan  | Processor failure due to heat stress or physical impact, exact match needed for DG43NB motherboard | \$200  |
| Ituner               | M4-ATX   | Power supply for ATX PC, 250W output, 6-30VDC input; provides all PC power voltages, uses 24 VDC TOGA power                     | Voltage output failure to PC. Unique form factor   | \$90   |
| Astrodyne            | LFM100-24  | 100 W ultraminiature, 24 VDC open frame switching power supply for the Ituner, uses UPS AC input makes 24 VDC for Ituner supply | Voltage output failure, miniature power supply   | \$150  |
| National Instruments | PCIe-6343  | PCIexpress, x-series DAQ card, ~20W spec  | Board failure would show up as a communication problem with LabVIEW or erroneous                   | \$1049 |

r  
u  
m  
e  
n  
t  
s

input/output values

|   |                |   |  |        |
|---|----------------|---|--|--------|
| National<br>I<br>n<br>s<br>t<br>r<br>u<br>m<br>e<br>n<br>t<br>s | PCI-8430/4     | PCI bus to 4 channel serial I/O                               | Board failure would show up as missing COM ports or erratic serial behavior                  | \$449  |
| National<br>I<br>n<br>s<br>t<br>r<br>u<br>m<br>e<br>n<br>t<br>s | PCI-6713       | PCI bus to 8 channel D/A                                      | Erroneous or missing analog output signals   | \$1399 |
| National<br>I<br>n<br>s<br>t<br>r<br>u<br>m<br>e<br>n<br>t<br>s | CB-68LPR       | A/D breakout racks, 777145-02<br>Or is it: 184700D-01L        | Impact breakage or stripped threads in the wire fastening screws, exact form factor critical | \$99   |
| Murata  | BMP-15/1.3-D24 | 24 VDC to +/- 15 VDC for FCs<br>1.3 A @+ and - 15VDC, 85% eff | Failure would show up as a loss of all flow controller operation                             | \$150  |
| Adixen  | ACT 100 OEM    | Adixen controller for molecular                               | Molecular drag pump would  | \$1000 |

board

drag pump

not operate. This board and the 5011 pump are critical for TOGA operation.

|       |           |  |   |       |
|-------|-----------|--|---|-------|
| Vicor | V1-J1H-CW | 100 W Vicor DC-DC power supply to be custom fit onto ACT 100 OEM board | Molecular drag pump would not operate. This supply powers the ACT 100 OEM board (above) | \$125 |
|-------|-----------|--|---|-------|

|       |  |   |   |       |
|-------|--|---|---|-------|
| Valco | EPCA-CE "Two position actuator control module" | Drive electronics module for 10 port valve, serial, 24 VDC, 48W | If this fails TOGA will not aspirate sample, no organics will be measured | \$400 |
|-------|--|---|---|-------|

|       |          |   |   |       |
|-------|----------|---|---|-------|
| Valco | EMTCA-CE | Drive electronics module for SSV, serial, 24 VDC, 48W, 10 pin double row connector to drive motor | If this fails TOGA will not aspirate sample, no organics will be measured | \$400 |
|-------|----------|---|---|-------|

|       |         |  |  |        |
|-------|---------|--|--|--------|
| Valco | EPC10WE | Valco 10 port valve, primary valve used in sample preconcentration | When/if the valve begins to wear/fail leaks will develop visible with mass spectrometer. TOGA performance will be horrible | \$1070 |
|-------|---------|--|--|--------|

|       |     |                            |   |       |
|-------|-----|----------------------------|---|-------|
| Valco | HPM | Electronic helium purifier | The purifier is a consumable with regular replacement necessary. ~every 6 months of Hiaper operation it should be replaced. Failure is seen as poor TOGA blanks | \$450 |
|-------|-----|----------------------------|---|-------|

|     |                                |   |  |       |
|-----|--------------------------------|---|--|-------|
| KNF | Pump rebuild kit for model 828 | Pump is model 828, brushless, 24VDC, the clean air generator pump | Rebuild is indicated when CAG cannot reach 3 slpm at altitudes below 25kft | \$150 |
|-----|--------------------------------|---|--|-------|

|                  |                     |                                 |   |        |
|------------------|---------------------|---------------------------------|---|--------|
| Senior flexonics | Bellows rebuild kit | The internal pumping components | Bellows failure will be catastrophic with performance normal until the bellows breaks in one side of the pump | \$1000 |
|------------------|---------------------|---------------------------------|---|--------|

|     |                                     |   |  |       |
|-----|-------------------------------------|---|--|-------|
| KNF | Rebuild kit for MPU 1091-N84.0-8.99 | Diaphragm and valve pieces for the rough pump | Pump will not achieve operational pressure (pump down below 20 Torr) during TOGA powerup cycle. Software should alert user of rough pump failure | \$150 |
|-----|-------------------------------------|---|--|-------|

|     |                                   |  |  |       |
|-----|-----------------------------------|--|--|-------|
| KNF | Rebuild kit for UNPK09 BLDC 24VDC | High P pneumatic pump, generates air for Clippard actuators and pneumatic valves | Pump will not achieve operational pressure (P > 40 psig) during TOGA powerup cycle. Software should alert user of rough pump failure | \$150 |
|-----|-----------------------------------|--|--|-------|

|          |            |                             |                              |         |
|----------|------------|-----------------------------|------------------------------|---------|
| Clippard | EC-3M-24-E | Actuator valves, EPR seals, | Valve can fail at high cycle | \$50 ea |
|----------|------------|-----------------------------|------------------------------|---------|

Rep is  
at 303  
377  
2736

24VDC

number or if liquid  
water contaminates  
system. Silica gel  
may be red  
(saturated) and  
TOGA performance  
will be erroneous,  
indicative of  
particular flows not  
switching correctly

|          |                  |  |  |            |
|----------|------------------|--|--|------------|
| Clippard | 11923-pkg        | Manifold to 1/8" tubing connectors                                 | Normally won't fail unless overtightened during valve servicing  | \$30       |
| Tylan    | FC-280           | 10 sccm mass flow controller for GC column flow                    | Chromatography will be "off" or inoperative if this MFC fails  | \$1000     |
| Tylan    | FC-280           | 100 sccm flow controller, general use MFC                          | TOGA sample preconcentration will be erroneous   | \$1000     |
| Tylan    | FC-280           | 10 slpm flow controller, cooling N2 flow                           | One or more of the traps will not cool   | \$1000     |
| Unit     | 8160             | 10 slpm flow controller for primary inlet air control              | Primary sample inlet airflow will be too low, even at low altitudes  | \$1000     |
| SOLA     | S1K650           | 650 VA, 390 W output UPS   | If PC can't boot due to no input AC signal at the LFM100-24 power supply the UPS battery or main board may have failed. This is a stressed component. Exact form factor of battery and board critical. | \$300      |
| Varian   | TV-301 Navigator | turbo pump, the primary high vacuum pump for the mass spectrometer | As the bearings age or other fault occurs the pump won't operate and mass spectrometer pressure will be too high (>10 <sup>-4</sup> Torr), may initially be accompanied by whining noise               | \$11,000   |
| Agilent  | G-0861           | 5973N chamber side board electronics                               | MS high voltage or MS ion transmission won't occur. Agilent software should notify user  | \$2000     |
| Agilent  | G-3170-60050     | Ionization filaments   | Agilent software will tell the user when the filaments fail  | 4@\$124 ea |

|   |                 |  |  |        |
|---|-----------------|--|--|--------|
| Agilent   | G-6150          | Electron multiplier  | Count signal becomes too high  | \$1500 |
| Granville<br>-<br>Phillips/B<br>rooks<br>Automati<br>on | Mini-ion 342    | Ion gauge module, incl. electronics,<br>Granville Phillips, power 24VDC<br>@12W max<br>Output: 1-8VDC where $P=10^{(volts - 9)}$ | 10 V (invariant) signal results<br>when the ion gauge is<br>inoperable. The signal may be<br>a blown filament or more<br>likely, high pressure in the MS<br>chamber                                      | \$1000 |
| Adixen  | MDP 5011        | Molecular drag pump, provides the<br>second stage MS pumping in TOGA   | The MDP tends to audibly<br>whine and cause vibration to<br>the hand prior to complete<br>failure. At failure the loss of<br>TOGA second stage pumping<br>will result in the turbo pump<br>not operating | \$5000 |
| Agilent   | RMSH-2          | He purifying cartridge To reside in<br>aircraft cabin, not rack area   | Contaminants evident if this<br>cartridge needs replacing  | \$230  |
| Delta<br>adsorbent<br>s                                 | SG48B5 or other | Silica gel trap and fittings for drying<br>Clippard air  | Indicator silica gel goes from<br>blue to red upon saturation with<br>water vapor  | \$49   |